

1. ~~KURIOT r sets oversight compatibility of motors cited~~

two

~~para 2 ref.~~ Pouching/~~the~~ complete VLS-2R triggers immediately whose parts directly interchangeable. Request return ~~inoperative~~ inoperative VLS-2R and spares~~back~~ upon receipt above units.

2. Complete system checks Hqs indicated normal and reliable ops under low to medium light levels. Request info concerning field strength levels of any ~~possible~~ possible RF energy in test area. Additional info concerning level of atmospheric turbulence encountered during tests also requested.

3. Optimum setting lens<sup>and</sup> sensitivity control quite critical. Also trigger requires five to ten minutes to stabilize after set up.

4. ~~KRM~~ KURIOT rep processing for TDY in event you require services after receipt above triggers.